

Chemicals

- Sublime® (Descaler)
- Alimex (Descaler)
- Morcon-10 (Descaler)
- Sum-Kool® (Descaler)
- Sur-Clean (Degreaser)

Chemical Equipment



Sublime® Skid

Xtra-Glean

Super Industrial Degreaser & Cleaner

Xtra-Clean Product Benefits

- Specially formulated for cleaning oily and greasy surfaces such as: oil rigs, engines, oilside of heat exchangers, pipes, cleaning vats, etc.
- Cuts time and costs from your most difficult cleaning applications
- Safe for ferrous and non-ferrous metals
- A synthetic detergent with anti-redeposition agents to provide a non-caustic cleaner
- pH of 13.0
- Designed to quickly lift and suspend oil and dirt
- Environmentally safe water-based industrial strength degreaser and cleaner
- Does not contain Phosphates, Petroleum Distillates, Chlorinated Hydrocarbons, Ethylene Glycol, Monobutyl Ether, Sodium Hydroxide
- Does not contain chemicals subject to the reporting requirements of SARA Title III
- Moderate heat will enhance cleaning time and efficiency
- Biodegradable, Non-Flammable, Non-Abrasive, Non-Corrosive and Non-toxic
- NSF Registered for categories A8 (Compound for use as general cleaning agents on all surfaces, or for use with steam or mechanical cleaning devices in all departments) and C1(Compound for use on all surfaces in inedible product areas and/or exterior areas).

Xtra-Clean Applications

- **Industrial Dilution** For cleaning dirt and grease from equipment, lift trucks, engines, pipes, motor shells, electric motors and machinery. Printers For cleaning ink from presses, walls and floors. (1:5) One part of Xtra-Clean to five parts of water
- Maintenance Dilution For oil rigs, engines, oilside of heat exchangers, pipes, conveyors, exhaust stains, machines, metal stock and welding equipment and greasy floors.(1:2) One part of Xtra-Clean to two parts of water
- Vat Dilution For cleaning greasy and carboned parts. (1:1) One part of Xtra-Clean to one part of water

1315 Belmeade Drive, Kingsport, TN 37664, Toll Free: (888) 355-6004, Tel: (423) 343-7552, Fax: (423) 343-7553, E-mail: sales@bartassociates.com,

E-mail: sales@bartassociates.com, Website: www.bartassociates.com





Super Industrial Degreaser & Cleaner

Directions

Circulate, soak, spray or wipe it on and rinse off thoroughly.

For best results in cleaning vats,

12 hours of mild heat and agitation followed
by pressure rinse is recommended.



Contains: Alkaline silicates. May be harmful if

swallowed. Can cause eye and skin irritation.

External: Flood with water and wash with vinegar.

Internal: Give lemon, grapefruit or orange juice freely,

follow with olive oil.

Eyes: Wash with 5-6% boric acid solution.

If irritation or pain persists, call physician.

KEEP OUT OF THE REACH OF CHILDREN

Technical Data

pH: 13.0
Color: Clear
Odor: Fresh

Density: 8.34 lbs/gal Flash Point: None

Rinse Ability: Completely
Type Cleaner Water Soluble

Degreaser

Active Ingredients: Detergents, Builders

Soluble Solvents

Degreasing Efficiency Excellent
Specific Gravity 1.045
Stability (Hot or Cold): Excellent
Ferrous Metals None
Non-Ferrous Metals None









